

Inspection Photos

Loc: 307666

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/19/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307666 | Date: 2/19/2025

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307666 | Date: 2/19/2025

Inspection Photos



Photo 3. Facing west along the fill slope.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307666 | Date: 2/19/2025

Inspection Photos



Photo 4. Facing toward the production pit. The fence around the pit is not maintained.

