

Inspection Photos

Loc: 307744

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/19/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the fill slope of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307744 | Date: 2/19/2025

Inspection Photos



Photo 2. Facing toward the cut slope and meter shed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307744 | Date: 2/19/2025

Inspection Photos



Photo 3. Facing toward the wellsite and production equipment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307744 | Date: 2/19/2025