

Inspection Photos  
Location Name: LF Layer Unit 2  
Location ID: 318504



Photo 1 Location.

Photo 2 Wellhead Valves open.

Inspection Photos  
Location Name: LF Layer Unit 2  
Location ID: 318504



Photo 3 Wellhead sign.

Photo 4 Ancillary equipment, Electric panel is off.