

Inspection Photos
Location Name: Donald B Smith Unit 1
Location ID: 318252



Photo 1 Location.



Photo 2 Wellhead Valves open.

Inspection Photos
Location Name: Donald B Smith Unit 1
Location ID: 318252




Photo 3 Wellhead sign.




Photo 4 Ancillary equipment, Electric panel is off.

