

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422




Photo # 7589 From entrance to location

Photo # 7590 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7591 Location



Photo # 7592 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7593 Location



Photo # 7594 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7595 Location



Photo # 7596 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7597 Staining



Photo # 7598 Staining

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7599 Staining



Photo # 7600 Staining

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7601 Staining



Photo # 7602 Staining

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7603 Staining



Photo # 7604 Staining

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC DUANE SCOTT 1 Pad

Location ID: 335422



Photo # 7605 Staining



Photo # 7606 Staining