

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28SWNW

Location ID: 324145

Date: 2/19/2025



Location – Photo #06727

Location – Photo #06725

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28SWNW

Location ID: 324145

Date: 2/19/2025



Feb 19, 2025 at 11:35:57
5325 CR-215
Parachute CO 81635
United States



Feb 19, 2025 at 11:38:22
5325 CR-215
Parachute CO 81635
United States

Location – Photo #06726

Damaged Culvert – Photo #06728

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28SWNW

Location ID: 324145

Date: 2/19/2025



Damaged Culvert – Photo #06729