

Inspection Photos  
Location Name: GREENLAUGH, NAUMAN #1-23  
Location ID: 320150



Photo #1 Tanks.



Photo #2 Separator.

**Inspection Photos**  
**Location Name: GREENLAUGH, NAUMAN #1-23**  
**Location ID: 320150**



**Photo #3 ECDs.**



**Photo #4 Pump jack.**