

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is
approximately 290 yards from Multa Trina Ditch.**

Section/Township/Range:



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad
Location ID: 334629



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad
Location ID: 334629



Photo # 7209 Lack of stabilization/sloughing/wildlife hazard



Photo # 7210 Lack of stabilization/sloughing/wildlife hazard