

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6921 From entrance to location



Photo # 6922 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6923 Location



Photo # 6924 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6925 Location



Photo # 6926 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6927 Location



Photo # 6928 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Feb 19, 2025 at 12:02:34 PM
CO

Photo # 6929 Location



Feb 19, 2025 at 12:16:25 PM
CO

Photo # 6930 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6931 Hole in liner/liner needs maintenance



Photo # 6932 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6933 Hole in liner/liner needs maintenance



Photo # 6934 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Feb 19, 2025 at 12:30:32 PM
CO

Photo # 6935 Hole in liner/liner needs maintenance



Feb 19, 2025 at 12:25:57 PM
CO

Photo # 6936 Tank label lacks capacity

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6937 Tank label lacks capacity




Photo # 6938 Tank label lacks capacity

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo #05946 From inspection 708303308 conducted on 01/14/2025 Unused Equipment



Photo # 6939 Unused Equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6940 Multiple holes in tank/tank lacks integrity



Photo # 6941 Multiple holes in tank/tank lacks integrity

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 11A-35-692 Pad

Location ID: 335001



Photo # 6942 Multiple holes in tank/tank lacks integrity



Photo # 6943 Multiple holes in tank/tank lacks integrity