

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC PLATZER 33B-27-692 Pad

Location # 335127



Photo # 6723 From entrance to location



Photo # 6724 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC PLATZER 33B-27-692 Pad

Location # 335127



Photo # 6725 Location



Photo # 6726 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC PLATZER 33B-27-692 Pad

Location # 335127



Photo # 6727 Location



Photo # 6728 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC PLATZER 33B-27-692 Pad

Location # 335127



Photo # 6729 Location



Photo # 6730 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC PLATZER 33B-27-692 Pad

Location # 335127



Photo # 6731 Tank label weathered & some required information is illegible




Photo # 6732 Tank label weathered & some required information is illegible

