

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Photo # 7726 From entrance to location




Photo # 7727 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Photo # 7728 Location



Photo # 7729 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Photo # 7730 Location



Photo # 7731 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Feb 20, 2025 at 11:06:34 AM
CO



Feb 20, 2025 at 11:09:52 AM
CO


Photo # 7732 Location

Photo # 7733 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Feb 20, 2025 at 11:09:18 AM
CO

Photo # 7734 Location



Feb 20, 2025 at 11:08:39 AM
CO

Photo # 7735 Stored equipment

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Dixon Federal Pad (SWNW-23-692) 11A-23-692

Location # 425899



Photo # 7736 Open ended load line

