

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4

Location ID: 334813

Date: 2/19/2025



Location Overview – Photo #06733



Location – Photo #06742

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4

Location ID: 334813

Date: 2/19/2025



Location – Photo #06734



Location – Photo #06743

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4


Location ID: 334813

Date: 2/19/2025



Feb 19, 2025 at 12:16:33
950 County Road 309
Parachute CO 81635
United States

Location – Photo #06746



Feb 19, 2025 at 12:15:56
950 County Road 309
Parachute CO 81635
United States

Location – Photo #06744

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4

Location ID: 334813

Date: 2/19/2025



Location – Photo #06741



Weathered Wellhead Sign – Photo #06735



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4

Location ID: 334813

Date: 2/19/2025



Weathered Wellhead Sign – Photo #06736



Weathered Wellhead Sign – Photo #06737

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4

Location ID: 334813

Date: 2/19/2025



Weathered Wellhead Sign – Photo #06738



Weathered Wellhead Sign – Photo #06739

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, Savage/GV 80-4

Location ID: 334813

Date: 2/19/2025



Weathered Wellhead Sign – Photo #06740



Damaged Battery Fencing – Photo #06745