

WELL NAME: NAPOLEAN 12-10, API #: 071-09043, INSP. # 716300528



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: LARGE AREA OF IMPACTED SOIL AROUND COMPRESSOR INSIDE AND OUTSIDE OF SOUND MITIGATION SHED. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED (REPAIR LEAKING EQUIPMENT).





PHOTO 5: OILY WASTE IN ENGINE SKID. PHOTO 6: LEAKS ON COMPRESSOR MOTOR AND EQUIPMENT. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. PER RULE 1002,(2).D. Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED, EQUIPMENT MUST BE REPAIRED.





PHOTO 6: MOST OF THE ENTIRE MOTOR AND SKID IS COVERED WITH OIL.

