

Inspection Photos

API: 011-05057

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 2/21/2025

County: Prowers



Inspection Photos



Photo 1. Drone photo (taken on 5/8/24) facing down toward the wellsite. There is an area with no vegetation which appears impacted soil from a historical spill.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-05057 | Date: 2/21/2025

Inspection Photos



Photo 2. Drone photo (taken on 2/4/25) facing down toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing northeast toward the wellsite. The concrete has been busted up and piled on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing toward the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05057 | Date: 2/21/2025