

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Photo 1: Wellhead Sign



Photo 2: TA Wellhead, overgrown vegetation removed



Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Photo 3: Tank Battery Sign



Photo 4: Base damaged

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Photo 5: Base damaged