

Inspection Photos

February 24th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 324971

Inspection Document #: 714001869

La Plata County, CO

Township: NESW 24 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Allison Unit 19
Location ID: 324971

2/24/25
+37.002316,-107.562685
243° SW



Photo 1. View of the well pad taken from the access point facing center.



2/24/25
+37.002019,-107.562997
339° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05008

Inspection Photos
Location Name: Allison Unit 19
Location ID: 324971

2/24/25
+37.002289,-107.562800
234° SW



2/24/25
+37.002238,-107.563019
275° W




2/24/25
+37.002125,-107.563215
218° SW



Photo 3. Interim reclamation exclusion sign and fence installed on the western edge of the pad.

Inspection Photos
Location Name: Allison Unit 19
Location ID: 324971





2/24/25
+37.001745,-107.563386
240° SW

