

Inspection Photos

February 24th, 2024

Operator: Dugan Production Corp - 25250

Location ID: 325497

Inspection Document #: 714001876

La Plata County, CO

Township: SWSE 11 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Tiffany 2
Location ID: 325497



Photo 1. View of the well pad taken from the access point facing center. Note: no local emergency number (ie. 911) posted to location sign.



API #: 067-06497

Inspection Photos
Location Name: Tiffany 2
Location ID: 325497



Photo 2. Rutting observed at access road and along perimeter of pad.

Inspection Photos
Location Name: Tiffany 2
Location ID: 325497

2/24/25
249° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Wildlife netting at produced water tank has ripped and is no longer functioning.

API #: 067-06497

2/24/25
268° W



Inspection Photos
Location Name: Tiffany 2
Location ID: 325497

2/24/25
1° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Juniper, Sagebrush and Indian Ricegrass.

API #: 067-06497