

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NENE**  
**Location ID: 335378**  
**Date: 2/21/2025**

**Location ID: 335378**

Date: 2/21/2025



**Location – Photo #06785**



**Location – Photo #06788**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NENE

Location ID: 335378

Date: 2/21/2025



Insufficient Erosion Control – Photo #06786



Insufficient Erosion Control – Photo #06787



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NENE

Location ID: 335378

Date: 2/21/2025



Location/Lack of Stabilization – Photo #06791



Insufficient Tracking BMPs – Photo #06790