

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO/PA 443-34

Location ID: 428684

Date: 2/21/2025



Location Overview – Photo #06793



Location – Photo #06800

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO/PA 443-34

Location ID: 428684

Date: 2/21/2025



Location – Photo #06794




Location – Photo #06795

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO/PA 443-34

Location ID: 428684

Date: 2/21/2025



Tank Label Needs Replaced – Photo #06797



Lack of Stabilization – Photo #06798

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO/PA 443-34

Location ID: 428684

Date: 2/21/2025



Lack of Stabilization – Photo #06799



Insufficient Tracking BMPs – Photo #06802