

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO-66S95W/34NESW

Location ID: 334570

Date: 2/21/2025



Location Overview – Photo #06804



Location Overview – Photo #06805

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO-66S95W/34NESW

Location ID: 334570

Date: 2/21/2025



Location – Photo #06806



Location – Photo #06811

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO-66S95W/34NESW

Location ID: 334570

Date: 2/21/2025



Location – Photo #06807



Lack of Stabilization – Photo #06810



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT/TOSCO-66S95W/34NESW

Location ID: 334570

Date: 2/21/2025



Insufficient Tracking BMPs – Photo #06812