

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Feb 24, 2025 at 2:33:59 PM
CO



Feb 24, 2025 at 3:10:22 PM
CO

Photo # 8620 From entrance to location

Photo # 8621 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8622 Location



Photo # 8623 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8624 Location



Photo # 8625 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8626 Location



Photo # 8627 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8628 Location



Photo # 8629 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8630 Location



Photo # 8631 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8632 Plow truck



Photo # 8633 Tank battery lacks required signage

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8634 Location



Photo # 8635 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8636 Unused equipment



Photo # 8637 ECD completely disconnected & not in use /unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 33A-35-692 Facility

Location ID: 413720



Photo # 8638 Dumpster open & available for entry by wildlife/wildlife hazard



Photo # 8639 Dumpster open & available for entry by wildlife/wildlife hazard