

Construction and Stormwater Inspection

February 24, 2025

Operator: BISON IV OPERATING LLC- 10670

Location ID: 486771

Inspection Document #: 697505798

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Barracuda
Location ID: 486771



Photo 1. Photo taken from the entrance of location, facing North. Photo illustrates an Operator sign and the mailbox with permits.

Note- the Form 2A was not in the mailbox per Rule 406.c.



Photo 2. Photo taken west of the entrance to location, facing Northeast. Photo illustrates the Operator has installed a vehicle tracking control (VTC) device BMP. Operator plans to install an addition VTC near the Operator sign shown in Photo 1.

At the time of this inspection, there were no track out issues observed.

Inspection Photos
Location Name: Barracuda
Location ID: 486771



Photo 3. Photo taken from the entrance of location off CR 74, facing Southwest. Photo illustrates there was no track out issues observed at the time of this inspection.



Photo 4. Photo taken from the western portion of location, facing North. Photo illustrates a perimeter stormwater BMP (ditch and berm with filtrex wattles) have been installed along the entire perimeter of location.

Inspection Photos
Location Name: Barracuda
Location ID: 486771



Photo 5. Photo taken from the northwestern perimeter of location, facing East. See comments under Photo 4.

Note- fugitive dust was observed during construction activities and can be observed in the background of the photo.



Photo 6. Photo taken from the northwestern perimeter of location, facing East. Photo illustrates the topsoil stockpile being stored along the northern perimeter of location.

At the time of this inspection, the Operator was performing topsoil salvage operations.

Note- fugitive dust was observed during construction activities and can be observed in the background of the photo.

Inspection Number: 697505798

Inspection Photos
Location Name: Barracuda
Location ID: 486771

DSCN4405



Photo 7. This is a screenshot from a video taken approximately at 10am illustrating fugitive dust from construction activities that blew in a southeastern direction.

Note- fugitive dust inhibits the background landscape.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 697505798



Photo 8. This is a screenshot from a video taken approximately at 2pm illustrating fugitive dust has been mitigated from construction activities.

Note- the background landscape is visible now.