

Operator: Crestone Peak Resources Operating LLC

Location Name: Rodman Bruntz 26H-D266 FAC

Loc ID: 330697

Inspection: 714300154

CA: Spill excavations have been backfilled and all equipment removed from location. No soil has been stockpiled on location. Operator shall provide an updated Form 27 for Remediation #35918 with a workplan and timeline for remediation of Spill ID 488192. Operator shall provide an updated Form 27 for Remediation #35916 with a workplan and timeline for remediation of Spill ID 488350.

CA Resolution: Operator has addressed the corrective action for Remediation #35918 with Form 27 Doc # 404018526 on 12/6/2024 and addressed the correction action for Remediation #35916 with Form 27 Doc # 404022879 on 12/10/2024.