

Operator: Extraction Oil & Gas
Location Name: Bliss 10-33 TB Loc
Loc ID: 448568
Inspection: 718700047

CA: After reviewing the Operator supplied drone imagery, it does not appear that the Bliss 10-33TB (448568) meets Rule 1004 vegetative compliance. The reclaimed tank battery is not reflective of the adjacent reference areas as evidenced by stunted crop growth which could be a result of soil suitability or compaction issues. Additional reclamation activities are required. Refer to attached inspection photos. Perform reclamation in accordance with Rule 1004.

CA Resolution: Operator has addressed the issue with Form 4 Doc # 404090610.