

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 2/24/2025



Location Overview – Photo #06824



Location – Photo #06828

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 2/24/2025



Location – Photo #06827



Location – Photo #06826

Inspection Photos


Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 2/24/2025



Location – Photo #06825



Lack of Stabilization – Photo #06831

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON D20 696

Location ID: 335161

Date: 2/24/2025



Lack of Stabilization – Photo #06834



Insufficient Tracking BMPs – Photo #06835