

Inspection Photos  
Location Name: Walter Hunziker 1  
Location ID: 317633



Photo 1 Location

Photo 2 Dead vegetation at the Tank battery.

Inspection Photos  
Location Name: Walter Hunziker 1  
Location ID: 317633



Photo 3 tank battery sign.

Photo 4 Tank battery.

Inspection Photos  
Location Name: Walter Hunziker 1  
Location ID: 317633



Photo 5 Gas meter Run.



Photo 6 Produced water tank.

Inspection Photos  
Location Name: Walter Hunziker 1  
Location ID: 317633



Photo 7 Horizontal heated Separator.

Photo 8 Wellsite.

Inspection Photos  
Location Name: Walter Hunziker 1  
Location ID: 317633



Photo 9 Wellhead.



Photo 10 Ancillary equipment.

Inspection Photos  
Location Name: Walter Hunziker 1  
Location ID: 317633



Photo 11 Wellhead sign.