

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 1 Location



Photo 2 Dead vegetation at the Tank battery.



Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 3 Tank battery sign.



Photo 4 Tank battery.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 5 Gas meter Run.



Photo 6 Vertical Separator.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 7 Horizontal heated Separator.



Photo 8 Wellsite.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 9 Wellhead.



Photo 10 Ancillary equipment.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 11 Wellhead sign.