

Inspection Photos

Location Name: North Platte/41-34 Pad

Location #: 413974



Photo #1

North Platte 41-34, 42-34 Wellsite(s)

Temporarily Abandoned | TA

Wellsite(s) entrance




Photo #2

North Platte 42-34 (123-35676) Wellsite

Temporarily Abandoned | TA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: North Platte/41-34 Pad

Location #: 413974




Photo #3

North Platte 41-34, 42-34 Battery site

Inactive | Shut-down

Formerly served:

North Platte 31-34, 32-34 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 413974



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources