

Inspection Photos

Location Name: North Platte/41-34 Pad

Location #: 413974



Photo #1

North Platte 41-34, 42-34

Battery site

Inactive | Shut-down

Battery entrance




Photo #2

North Platte 41-34, 42-34 Battery site

Inactive | Shut-down

Formerly served:

North Platte 31-34, 32-34 ;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: North Platte/41-34 Pad

Location #: 413974



Photo #3

North Platte 41-34, 42-34

Battery site

Inactive | Shut-down

Crude oil, Produced H₂O tank(s), vault(s): SE corner



Photo #4

North Platte 41-34, 42-34

Battery site

Inactive | Shut-down

Separator(s), ECD(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: North Platte/41-34 Pad
Location #: 413974



Photo #5
North Platte 41-34, 42-34
Battery site
Inactive | Shut-down
ECD(s)



Photo #6
North Platte 41-34, 42-34
Battery site
Inactive | Shut-down
Facility / Battery signage



Inspection Photos

Location Name: North Platte/P-T-34HZ Pad

Location #: 429920

Associated Well(s)	API	Status
1. North Platte 41-34	123-30518	TA
2. North Platte 42-34	123-35676	TA

Photo #7

North Platte 41-34, 42-34

Battery site

Inactive | Shut-down

Associated well(s)

2: Temporarily Abandoned | TA

N → S



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources