

**Inspection Photos**  
**Location: Santa Fe Ranch 24-12**  
**Location ID: 314207**  
**API # 05-099-06360**



**Photo 1 –Well placard**

**Photo 2 – Remediation area at wellhead**

**Inspection Photos**  
**Location: Santa Fe Ranch 24-12**  
**Location ID: 314207**  
**API # 05-099-06360**



**Photo 3 – Remediation area at wellhead**

**Photo 4 – Remediation area at wellhead**

**Inspection Photos**  
**Location: Santa Fe Ranch 24-12**  
**Location ID: 314207**  
**API # 05-099-06360**



**Photo 5 –Soil pile**



**Photo 6 – Remediation area at tank battery,  
temporary fence is not adequate**

**Inspection Photos**  
**Location: Santa Fe Ranch 24-12**  
**Location ID: 314207**  
**API # 05-099-06360**



**Photo 7 – Remediation area at tank battery,  
temporary fence is not adequate**

**Photo 8 – Remediation area at tank battery,  
temporary fence is not adequate**

**Inspection Photos**  
**Location: Santa Fe Ranch 24-12**  
**Location ID: 314207**  
**API # 05-099-06360**



**Photo 9 – Tank Battery excavation adjacent to county road, photo from county road**

**Photo 10 – Tank Battery excavation adjacent to county road, photo from county road**