

# Final Reclamation Inspection

February 24, 2025

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC- 8960

Location ID: 420169

Inspection Document #: 697505800

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: State 7-62-36  
Location ID: 420169



**Photo 1.** Photo taken from the well location entrance, facing West. Photo illustrates the two-track access road continues west implying that the access road was pre-existing to oil and gas activity.



**Photo 2.** Photo taken from the well location entrance, facing East. Photo illustrates the main access road is stabilized with no erosion issues.




Inspection Photos  
Location Name: State 7-62-36  
Location ID: 420169



**Photo 3.** Photo taken from the well location entrance, facing South. Photo illustrates the well location access road. Operator has removed gravel and some establishment was observed throughout portions of the access road.

Note- well location is fenced in the background.



**Photo 4.** Photo taken from the southern well location access road, facing North. See comments under Photo 3.



Inspection Photos  
Location Name: State 7-62-36  
Location ID: 420169



**Photo 5.** Photo taken from the northeast well location, facing West. Photo illustrates the Operator has performed final reclamation activities. Some establishment was observed throughout portions of the location.



**Photo 6.** Photo taken from the northeast well location, facing South. See comments under Photo 5.



Inspection Photos  
Location Name: State 7-62-36  
Location ID: 420169



**Photo 7.** Photo taken from the central well location, facing South. See comments under Photo 5.



**Photo 8.** Photo taken from the central well location, facing East. See comments under Photo 5.