

Inspection Photos

02/24/2025

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location ID: 397164

Inspection Doc: 718100276

Rio Blanco County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 397164



Photo 1: Photos 1-2 taken from the south end of the Location, facing northwest, north, northeast to east. Location, including the former access road, appear to be predominantly bare and exposed soils with sparse perennial vegetative establishment. Vegetation on the remaining areas of the Location are predominantly undesirable plant species such as Salsola, Kochia, and/or mustard.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 397164



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location ID: 397164



Photo 3: Photos examples showing the location, including the former access road, appear to be predominantly bare and exposed soils with sparse perennial vegetative establishment. Vegetation on the remaining areas of the Location are predominantly undesirable plant species such as Salsola, Kochia, and/or mustard.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources