

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B

Location # 311685



Photo # 9248 From entrance to location



Photo # 9249 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B

Location # 311685



Photo # 9250 Location



Photo # 9251 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B

Location # 311685



Photo # 9252 Location



Photo # 9253 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B

Location # 311685



Photo # 9254 Staining near wellhead



Photo # 9255 Same area of staining near wellhead from another angle

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 3-31B

Location # 311685



**Photo # 9256 Dumpster open & available for entry by wildlife/wildlife hazard**



**Photo # 9257 Dumpster closed by TEP employee during inspection**