

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 2/25/2025



Location – Photo #06857



Location – Photo #06860

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 2/25/2025



Location – Photo #06862



Location – Photo #06858

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 2/25/2025



Location – Photo #06865



Lack of Stabilization – Photo #06861

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 2/25/2025



Lack of Stabilization – Photo #06859



Insufficient Tracking BMPs – Photo #06864