

# Final Reclamation and Stormwater Inspection

February 14, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 319933

Well Name: CHAMPLIN 117 G #4

Inspection Document #: 718600293

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CHAMPLIN 117 G #4  
Location ID: 319933



**Photo 1.** Looking south towards access road. It appears that gravel was removed from the well location and that reclamation work was conducted. The remaining access road is being used as a driveway.



**Photo 2.** Looking east across well location. There appears to be remains of crimped straw on location. There is poor vegetative establishment. Undesirable weeds Russian Thistle and Kochica are present on location.



Inspection Photos  
Location Name: CHAMPLIN 117 G #4  
Location ID: 319933



**Photo 3.** No oil and gas equipment remains on location. List C noxious weed mullein was not present on location at time of inspection but is present adjacent to the location. The t-posts in this image appear to be related to landowner fencing.



**Photo 4.** Reference vegetation to the north of the well location.