

Inspection Photos

Location: #380893

Operator: WAVETECH HELIUM INC

Inspection Date: 2/26/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos




Photo 2. Facing west toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380893 | Date: 2/26/2025

Inspection Photos



Photo 3. Facing toward the tank battery. The earthen berm is not designed to resist degradation from erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380893 | Date: 2/26/2025

Inspection Photos



Photo 3. There are animal borrows in the side of the berm. The earthen berm is not designed to resist degradation from erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380893 | Date: 2/26/2025

Inspection Photos



Photo 4. North side of the location facing south. Unused areas of the location have not been reclaimed.



Inspection Photos



Photo 5. Drone aerial photo facing southwest toward the location.



Inspection Photos



Photo 6. Drone aerial photo facing east toward the location.



Inspection Photos



Photo 7. Drone aerial photo facing southeast toward the topsoil pile. There is erosion occurring along the topsoil pile.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380893 | Date: 2/26/2025