

Inspection Photos

Loc: 485672

Operator: WAVETECH HELIUM INC

Inspection Date: 2/26/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicles are avoiding the eroded area of the road causing unnecessary disturbance. The road needs to be repaired and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485672 | Date: 2/26/2025

Inspection Photos



Photo 2. Facing south along the access road. The access road needs to be reduced in size by reclaiming and decompacting soils.



Inspection Photos



Photo 3. Facing south toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485672 | Date: 2/26/2025

Inspection Photos




Photo 4. Facing toward the wellhead. There are stained soils shown at red arrow that need to be cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485672 | Date: 2/26/2025

Inspection Photos



Photo 5. It appears some of the grey cuttings previously observed along the eastern side were removed. There appear to be some discolored soils that remain.



Inspection Photos




Photo 6. Drone aerial photo facing south toward the location. Interim reclamation has not been completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:485672 | Date: 2/26/2025

Inspection Photos



Photo 7. Drone aerial photo facing northwest toward the location. Interim reclamation has not been completed.

