

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639



Photo 1 Dead vegetation lying around Location

Photo 2 Gas Meter run not calibrated.

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639



Photo 3 Dead vegetation around Vertical Separator.

Photo 4 Dead vegetation around Gas Meter run not calibrated.

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639




Photo 5 Dead vegetation around Vertical Separator.

Photo 6 Dead vegetation around Vertical separator.

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639



Photo 7 Tank battery no signage, berms need work.

Photo 8 Tank battery no signage, berms need work.

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639



Photo 9 Flow line manifold dead vegetation throughout location.

Photo 10 Dead vegetation around Well site.

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639



Photo 11 Wellhead

Photo 12 Dead vegetation around Wellsite sign.

Inspection Photos  
Location Name: Martin T Hart 1  
Location ID: 317639



Photo 13 Dead vegetation around the ancillary equipment.

Photo 12 Wellsite sign.