

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 27
Location ID: 480511 Tank Battery 480510
Spill ID # 488412 and Spill ID 489069



Photo 1 –Placard

Photo 2 – Remediation area with impacts

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 27
Location ID: 480511 Tank Battery 480510
Spill ID # 488412 and Spill ID 489069



Photo 3 – Remediation area with impacts

Photo 4 – Remediation area with impacts

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 27
Location ID: 480511 Tank Battery 480510
Spill ID # 488412 and Spill ID 489069



Photo 5 – Remediation area with impacts

Photo 6 – Remediation area with impacts

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 27
Location ID: 480511 Tank Battery 480510
Spill ID # 488412 and Spill ID 489069



Photo 7 –Tank

Photo 8 – Contaminated soils on tarp

Inspection Photos

Location: Arapahoe Unit Tank Battery Sec. 27

Location ID: 480511 Tank Battery 480510

Spill ID # 488412 and Spill ID 489069



Photo 9 – Tank battery and equipment

Photo 10 – Tank battery and equipment

Inspection Photos

Location: Arapahoe Unit Tank Battery Sec. 27

Location ID: 480511 Tank Battery 480510

Spill ID # 488412 and Spill ID 489069



Photo 11 –Tank



Photo 12 – Spoil Pile