

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 28
Location ID: 321676 Tank Battery 480502
Spill ID # 484570



Photo 1 –Placard

Photo 2 – Remediation area with impacts

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 28
Location ID: 321676 Tank Battery 480502
Spill ID # 484570



Photo 3 – Tank battery

Photo 4 – Location equipment

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 28
Location ID: 321676 Tank Battery 480502
Spill ID # 484570



Photo 5 – Spoil Pile and impacted soils

Photo 6 – Spoil pile

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 28
Location ID: 321676 Tank Battery 480502
Spill ID # 484570



Photo 7 –Tank

Photo 8 – Flowline to tank

Inspection Photos
Location: Arapahoe Unit Tank Battery Sec. 28
Location ID: 321676 Tank Battery 480502
Spill ID # 484570



Photo 9 – Impacted soils



Photo 10 – Tank battery and equipment