

Inspection Photos

February 27th, 2025

Operator: Simcoe LLC - 10749

Location ID: 334276

Inspection Document #: 714001892

La Plata County, CO

Township: SWSE 13 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neil 34-13 1
Location ID: 334276



Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07778

2/27/25
317° NW



Photo 2. Separator labels have deteriorated and are no longer legible.

Inspection Photos
Location Name: Neil 34-13 1
Location ID: 334276



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Erosion forming on the western edge of the pad.

API #: 067-07778

Inspection Photos
Location Name: Neil 34-13 1
Location ID: 334276

2/27/25
161° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. No unused equipment/debris observed on the pad.

API #: 067-07778