

# Inspection Photos

February 27th, 2025

Operator: Simcoe LLC - 10749

Location ID: 307031

Inspection Document #: 714001894

La Plata County, CO

Township: SESE 19 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

2/27/25  
325° NW



Photo 1. View of the well pad taken from the access point facing center.

2/27/25  
358° N



**Photo 2.** View of the eastern interim reclamation area composed predominantly of Western Wheatgrass and Prairie Sunflower.



**Photo 3.** Stormwater BMPs installed in the eastern portion of the pad.

