

Inspection Photos

February 27th, 2025

Operator: Simcoe LLC - 10749

Location ID: 326331

Inspection Document #: 714001898

La Plata County, CO

Township: SESE 20 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kight D1
Location ID: 326331



Photo 1. View of the well pad taken from the access point facing center. Note: location sign is deteriorating and some information is not legible, current operator sticker peeling,



API #: 067-07850

Inspection Photos
Location Name: Kight D1
Location ID: 326331

2/27/25
22° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Previously unused sound panels have been reinstalled on location.

API #: 067-07850

Inspection Photos
Location Name: Kight D1
Location ID: 326331

2/27/25
335° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Interim reclamation area composed of Western Wheatgrass and Smooth Brome.

API #: 067-07850

Inspection Photos
Location Name: Kight D1
Location ID: 326331

2/27/25
257° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Irrigated grass/active pasture reference area.

API #: 067-07850