

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/26/2025



Location Overview – Photo #06877



Location – Photo #06878

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/26/2025



Berm Liner Separating From Containment – Photo #06880



Berm Liner Separating From Containment – Photo #06881

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/26/2025



Berm Liner Separating From Containment – Photo #06882