

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S95W/3NENE

Location ID: 334647

Date: 2/26/2025



Location – Photo #06886

Location – Photo #06889

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S95W/3NENE

Location ID: 334647

Date: 2/26/2025



Location – Photo #06888



Location – Photo #06891

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S95W/3NENE

Location ID: 334647

Date: 2/26/2025



Location – Photo #06890



Lack of Stabilization – Photo #06887

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S95W/3NENE

Location ID: 334647

Date: 2/26/2025



**Insufficient Tracking BMPs – Photo #06892**