

Inspection/Audit Photos

Location Name: QB Energy BENZEL 36-15B (K36B) Pad

Location #: 334899



Photo # 150 From entrance to location



Photo # 151 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-15B (K36B) Pad
Location #: 334899



Photo # 152 Location



Photo # 153 Location



Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-15B (K36B) Pad
Location #: 334899



Photo # 154 Location



Photo # 155 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB Energy BENZEL 36-15B (K36B) Pad

Location #: 334899



Photo # 156 Holes in liner/liner needs maintenance



Photo # 157 Hole in liner/liner needs maintenance



Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-15B (K36B) Pad
Location #: 334899



Photo # 158 Holes in liner/liner needs maintenance



Photo # 159 Hole in liner/liner needs maintenance