

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA UNIT #63

Location ID: 316848

API #: 05-113-06148

Inspection Date: 2/28/2025 Inspection Doc#: 693808041



Wellhead with fence



**Meter Housing with sign.
Disconnected.**



Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA UNIT #63


Location ID: 316848

API #: 05-113-06148

Inspection Date: 2/28/2025 Inspection Doc#: 693808041



Tank battery rusted and collapsed.



FLIR image of collapsed tank.

See attached video MOV_3706.MP4

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA UNIT #63

Location ID: 316848

API #: 05-113-06148

Inspection Date: 2/28/2025 Inspection Doc#: 693808041



Off location Flowline Riser and Valve



Location overview