

Inspection Photos
Location Name: Rhine 21-29 1
Location ID: 320760



Pic 1 Separator, ECD



Pic 2 stained soil by tanks

Inspection Photos
Location Name: Rhine 21-29 1
Location ID: 320760



Pic 3 Tanks work being done on location



Pic 4 tank sign

Inspection Photos
Location Name: Rhine 21-29 1
Location ID: 320760

Feb 27, 2025 at 1:13:22 PM
+39.593235,-104.354814
Arapahoe County
ECMC



Pic 5 Remediation work on location

Feb 27, 2025 at 1:13:26 PM
+39.593235,-104.354814
Arapahoe County
ECMC



Pic 6 equipment for tanks

Inspection Photos
Location Name: Rhine 21-29 1
Location ID: 320760



Pic 7 Wellhead / pumpjack



Pic 8 Wellhead sign

