

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8407 From entrance to location




Photo # 8408 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Feb 24, 2025 at 1:28:07 PM
CO

Photo # 8409 Location



Feb 24, 2025 at 1:25:43 PM
CO

Photo # 8410 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8411 Location



Photo # 8412 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8413 Location



Photo # 8414 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8415 Location



Photo # 8416 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674




Photo # 8417 Tank label contains inaccurate information/not in compliance with CECMC rules



Photo # 8418 Tank label damaged & missing required information/not in compliance with CECMC rules



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8419 Tank label damaged/some required information is becoming illegible & tank capacity incorrect /not in compliance with CECMC rules



Photo # 8420 Unused equipment



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8421 Unused equipment



Photo # 8422 Unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674




Photo # 8423 Tank not in service/unused equipment



Photo # 8424 Tank not in service/unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8425 Tank not in service/unused equipment



Photo # 8426 Tank not in service/unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8427 Tank not in service/unused equipment



Photo # 8428 Tank battery signage does not comply with CECMC signage rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 43A-35-692 Pad

Location ID: 334674



Photo # 8429 Secondary containment inadequate/does not comply with CECMC rules



Photo # 8430 Secondary containment inadequate/does not comply with CECMC rules