

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9493 From entrance to location



Photo # 9494 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9495 Location



Photo # 9496 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Feb 26, 2025 at 1:18:57 PM

Photo # 9497 Location



Feb 26, 2025 at 1:19:27 PM

Photo # 9498 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9499 Location



Photo # 9500 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9501 Location



Photo # 9502 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9503 Location



Photo # 9504 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9505 Sign at tank battery does not comply with CECMC tank battery signage rules

Photo # 9506 Sign at tank battery does not comply with CECMC tank battery signage rules



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Location ID: 418340



Photo # 9508 Unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340



Photo # 9509 Unused equipment




Photo # 9510 Tank label missing some required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Kaufman (Pad #4) 43D-25-692

Location ID: 418340




Photo # 9511 Tank label missing some required information

